

SPEC SHEET + MEASUREMENTS

PORT AUTHORITY.

Port Authority® Long Sleeve Denim Shirt. S600

Product photo



Showcase your logo on America's favorite fabric. You'll find versatility and reliability in our stonewashed denim shirt.

- 7-ounce, 100% cotton
- Double-needle stitching throughout
- Button-down collar
- Left chest pocket
- Rounded adjustable cuffs
- Due to special finishing process, colors may vary.

CARE INSTRUCTIONS

Machine wash cold with like colors. Do not bleach. Do not dry clean. Tumble dry low. Warm iron if necessary.

Sketches



front



back

SPEC SHEET + MEASUREMENTS

PORT AUTHORITY

Port Authority® Long Sleeve Denim Shirt. S600

PRODUCT MEASUREMENTS

	XS	S	M	L	XL	2XL	3XL	4XL	5XL	6XL
Chest	20	21 1/2	23	24 1/2	26	27 1/2	29	30 1/2	35 1/2	37
Sleeve Length	31	32 1/2	34 1/2	35 1/2	37	38	39	40	41	42
Neck	15 1/2	16	16 1/2	17	17 1/2	18	18 1/2	19	19 1/2	20
Body Length at Back	27	29	31	31 1/2	33	33 1/2	34 1/2	35	35 1/2	36
Pocket Height	5 1/2	5 1/2	6	6	6	6	6 1/4	6 1/4	6 1/4	6 1/4
Pocket Width	5	5	5 1/4	5 1/4	5 1/4	5 1/4	5 1/2	5 1/2	5 1/2	5 1/2

Chest: Measured across the chest one inch below armhole when laid flat.

Sleeve Length: Start at center of neck and measure down shoulder, down sleeve to hem.

Neck: Measured from center of button to center of buttonhole.

Body Length at Back: Measured from high point shoulder to finished hem at back.

Pocket Height: Measure from top to bottom at center.

Pocket Width: Measure from side to side at top edge.

SPEC SHEET + MEASUREMENTS


PORT AUTHORITY

Port Authority® Long Sleeve Denim Shirt. S600

SIZE CHARTS

	XS	S	M	L	XL	2XL	3XL	4XL	5XL	6XL	7XL	8XL	9XL	10XL
Chest	32-34	35-37	38-40	41-43	44-46	47-49	50-52	54-57	58-60	61-63	64-66	67-69	70-72	73-75
Neck	14	15	15	16	16	17	17	18	18	19	19	20	20	21
	1/2	-	1/2	-	1/2	-	1/2	-	1/2	-	1/2	1/4	3/4	1/4
	-	15	-	16	-	17	-	18	-	19	-	-	-	-
	15	1/2	16	1/2	17	1/2	18	1/2	19	1/2	20	3/4	21	3/4
Arm	30 1/2	32	34	35	36 1/2	37 1/2	38 1/2	39 1/2	40 1/2	41 1/2	41 1/2	41 1/2	41 1/2	41 1/2

HOW TO MEASURE



Neck Measure around the fullest part of the neck at the base.
Chest Width Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal. **Arm** Place hand on hip. Start at the center of the back of the neck and measure across the shoulder, to the elbow, and then down to the wrist.

COLORS



Faded Denim
PMS 3590C